## SOUTH DELHI MUNICIPAL CORPORATION OFFICE OF THE EXECUTIVE ENGINEER (AUTO) AUTO WORKSHOP NAJAGARH ZONE

NO. AE (AUTO)NGZ/25

DATED: 10:03:17-

S. NO	NAME OF SUPPLY / WORK	QUANTITY	HEAD OF A/C
01.	Stub Axle BEML Loader	01 No.	XL-IIIDIV
02.	a) Tube Repairing machine electric automatic	01 No.	do
	b) Tyre Cut Patch	02 Nos.	do
03.	a) Generator Alternator Coil	01 No.	do
	b) Insulation Tape	50 Nos.	do
	c) Ring Spanner (Assorted)	04 Nos.	do
	d) Screw Driver Double Side	02 Nos.	do
04.	a) Turbo Body TATA TC	01 No.	do
	b) Turbo Kit Complete TATA TC	01 No.	do
05.	Pressure Plate cover with spring set Eicher	01 No.	do
06.	a) Lift Jack Seal Kit TATA BS-IV	01 No.	do
	b) Lift Pump Seal Kit TATA BS-IV	01 No.	do
07.	Bucket Pin Bolt & Nut for Loader 17 No.	•	•
	3Inch	50 Nos.	do
08.	High Pressure Hose TATA BS-IV	01 No.	do
09.	Back Light Bulb TATA BS-IV 1141	150 Nos.	do
10.	Brake Pressure Hose TATA BS-IV	02 Nos.	do
11.	Pressure Sensor TATA BS-IV	01 No.	do
12.	a) Turbo Shaft TATA TC	01 No.	do
	b) Turbo Piston TATA TC	01 No.	do
13.	a) F.I.P. Nozzle Generator	2 Nos.	do
	b) Came Shaft Generator	01 No.	do
	c) Over Flow Pipe	01 No.	do
14.	High Pressure Hose BEML	01 No.	do
15.	Head Light Relay TATA BS-IV	26 Nos.	do
16.	a) Clutch Plate Eicher	01 No.	do
	b) Clutch Pipe	01 No.	do
17.	Water Proof Tirpal 24'x8' Heavy Duty with		
	Four Side Cotton Stitching & Ring Fixing	01 No.	do
18.	a) Stearing Pump Rottar Kit TATA BS-IV	01 No.	do
	b) Stearing Pump Sealing Kit	01 No.	do
	c) Stearing Pump Plate	01 No.	do
19.	Pressure Plate facing with leaver kit Eicher	01 No.	do
20.	Repairing of Cabin Shocker TATA BS-IV	04 Nos.	do
			A. 1

BM RAWAT
The list of the second of the secon

21.	Labour charges for dismantling Turbo Assy. and replacing body, kit, shaft & piston charge			
	including dismantling new bush p&fixing & machining, replacing parts and assembling and fixing on vehicle no. 5314 cattel catcher			
22.	and given satisfactory trial Repair of Tube Size 1000x20 with new	1 Job	do	
	Nulki fitting and burst repairing	8 Nos.	do	
23.	Rear both side brake system repairing & O/H of V No. DL-1GC-1377 i/c Rear both side brake system dismantling and brake drum turning & polishing, brake shoe welding & machining p&fixing Came bush, Came remering, Hub Greasing and brake system			
24.	completed and given a satisfactory trial Replacing and O/H of F.I. Pump of Genset i/c dismantling of F.I. Pump defected parts, plunger, barrel, spring & bearing new change. P&fixing F.I. Pump calibrating and given a	1 Job	do	
25.	satisfactory Trial Rear both side brake system repairing & O/H	1 Job	do	
	of V No. DL-1GC-1422 i/c Rear both side brake system dismantling and brake drum turning & polishing, brake shoe welding & machining, p&fixing Came bush, Came remering, Hub Greasing and brake system			
26.	completed and given a satisfactory trial Repairing & fixing of cabin jack foundation i/c Broken driver cabin floor repairing by gas weld and cabin jack foundation fixing and welding & given a satisfactory trial of V.No. 1469 TATA	•	do	
27.	BS-IV 1 Jobdo  Repairing and O/H of rear brake system of V.No.  1367 i/c dismantling of both side brake system, worn out brake lining cutting and hub drum turning. Brake lining fixing, both side wheel and hub oil seal replacing, both side hub greasing			
28.	and both side brake system assembling and give a satisfactory trial. Repairing & O/H of Stearing Pump Assembly i/	1 Job	do	
	Dismantling of Stearing Pump, worn out stearing Pump repairing kit P&fixing and given a satisfactory trial of V.No. DL-1GC-1364 TATA BS-IV 1 Jobdo			
29.	Repairing of Tube size 900x20 with valve body Fixing & burst repairing.	8 Nos.	do	
		- · • • •	141	

S. M. M. CANAT.

## **CONDITION**

- 1. The supply/work will have to be carried out as per schedule and within stipulated time.
- 2. The job to be carried out can be seen on any working day at Auto Workshop Najafgarh Zone.
- 3. The rate should hold good for 15 days from the date of opening the quotation.
- 4. If the material is not supplied / repaired within the prescribed date the same will be arranged from the second lowest at the cost and risk of lowest quotation.
- The authorities reserves the right of selection or rejection of lowest quotation or other lowest. The material rejected will have to be collected and taken back by the supplier at his own risk and cost.
- 6. It is further certified that the proposed bid / quotation of spare parts is not for the new vehicles which had been purchased in August 2013.

Assistant Engineer (AUTO) SIDMC Auto Workshop Najafgarh Zone

## Copy to:

1. C.V.O. South Delhi Municipal Corporation.

- 2. A.C.A. Najafgarh Zone for kind information and N/A please.
- 3. / Notice Board.
- With all cases.

5. A.O. (I.T.)

Misu Jana